From:	Flock Safety Support
To:	Stephen Best
Cc:	brendon.norton@flocksafety.com; Tee Jane Teh; libby.landers@flocksafety.com; Eligio Lara; Daniel Cohen; Stephen Best; jake.sherman@flocksafety.com; Michael Balcorta
Subject:	RE: And even more failures to read night plates
Date:	Friday, May 24, 2024 6:43:22 AM

*** EXTERNAL EMAIL: Please use caution when opening links or attachments.***

Good Morning,

Thank you. We'll have more details coming next week.

Have a great weekend,
Alex C

---------- Original Message ----------
From: Stephen Best [sbest@cityofsantamaria.org]
Sent: 5/24/2024, 9:35 AM
To: libby.landers@flocksafety.com; support@flocksafety.com; jake.sherman@flocksafety.com; brendon.norton@flocksafety.com
Cc: elara@cityofsantamaria.org; dcohen@cityofsantamaria.org; sbest@cityofsantamaria.org; mbalcorta@cityofsantamaria.org; tteh@cityofsantamaria.org
Subject: And even more failures to read night plates

Flock Safety Support,

I tested additional cameras for their ability to read license plates at night.

Of the 8 cameras I passed only 3 read my plate. That's about 37% success rate.

So this week, I've basically driving the width and length of the city four times and 80% of the Flock cameras I passed did not record my plate.

Today's test 05-24-24

CA/ 8LDA954

05:13:19 Hrs. Cam "001 SB Broadway (S of Taylor)" in lane 2 – Failed to read plate

05:14:00 Hrs. Cam "#01 SB N Broadway" (Big America's camera) in lane 2 -Success

05:15:20 Hrs. Cam "088 SB Broadway (S of Orchard)" in lane 2- Failed to read plate (This is on our main thoroughfare!)

05:16:57 Hrs. Cam "090 SB Broadway (S of Chapel)" in lane 2- Failed to read plate (main thoroughfare)

05:17:49 Hrs. Cam "028 SB Broadway (S of Orange)" in lane 2- failed to read plate (main thoroughfare)

05:19:32 Hrs. Cam "134 WB Stowell (W of Thornburg)" in lane 2- failed to read plate (main thoroughfare)

05:20:10 Hrs. Cam "023 SB Depot (S of Stowell)"- Success

05:22:23 Hrs. Cam "110 SB Thornburg (S of Carmen)" -Success

I searched all 220 cameras for 8LDA954 for 05-24-24 from 0500-0530 Hrs. Results=3 successful reads



I took a closer look at two of the cameras on our main thoroughfare and pulled all images from a 2 hour period 0330-0530 Hrs.

Cam “134 WB Stowell” had 21 images but only 10 plate reads

Cam “088 SB Broadway” @ orchard had 214 images but only 80 plate reads.

Also attached are the “all images” for the various cameras at the times I should have been passing by.

(A second email will have some additional attachments.)

Please add all these cameras to the list to be serviced.

Corporal Stephen L. Best

Santa Maria Police Department

1111 W. Betteravia Rd., Santa Maria, CA 93455

(805)928-3781 X2491

sbest@ci.santa-maria.ca.us

sbest@cityofsantamaria.org

WARNING! The information contained in this transmission is privileged and confidential. It is intended only for the use of the person(s) named above. If you are not the intended recipient, you are hereby notified that any review, dissemination, distribution or duplication of this communication is strictly prohibited. If you are not the intended recipient, please contact the sender by reply email and destroy all copies of the original message and any attachments.

To unsubscribe from this group and stop receiving emails from it, send an email to support+unsubscribe@flocksafety.com.

thread::DFFRp9J-JHui_y7qPzTTkg4::